

Riverside, MO 64150
Telephone: 816.231.5580
Fax: 816.231.5641
www.occutec.com

June 8, 2018

Ms. Diane Czarnecki
Industrial Hygienist
Facilities Management Division
GSA Public Buildings Service – Heartland Region
2300 Main Street
Kansas City, Missouri 64108

RE: Goodfellow Federal Center - Metals in Air Investigation
Buildings – 103E
4300 Goodfellow Boulevard
St. Louis, Missouri 63120
OCCU-TEC Project No. 918004

Dear Ms. Czarnecki:

Thank you for the opportunity to assist the General Services Administration (GSA) with the Resource Conservation and Recovery Act (RCRA) metals air sampling investigation of the above referenced buildings located at the Goodfellow Federal Complex, in St. Louis, Missouri. OCCU-TEC, Inc. (OCCU-TEC) understands that the purpose of the investigation was to provide sampling data regarding pre-existing conditions noted in investigation reports previously prepared for the facility. The following report summarizes the sample collection activities and the laboratory analytical results of the samples submitted.

On April 10, 2018, Missouri licensed air sampling professionals from OCCU-TEC conducted air sampling for the presence of seven (7) of the RCRA metals including Silver, Arsenic, Barium, Cadmium, Chromium, Lead, and Selenium. Sampling was conducted at Building 103E.

The proposed sampling scheme, the numbers of samples, sample distribution and general methodology was developed based on previous investigation methodology and in coordination with the GSA. Sample locations and samples collected from discretionary locations were determined by OCCU-TEC field personnel while on-site.

Resource Conservation and Recovery Act Metals Air Sampling

Air sampling for RCRA metals was collected on 37-millimeter (mm) cassettes with 0.8 micrometer (µm) mixed cellulose ester (MCE) filters using powered air sampling pumps in accordance with National Institute for Occupational Safety and Health (NIOSH) sampling methodology. Samples were collected in a method sufficient to collect a minimum sample volume of 300 liters. Air samples were submitted under chain-of-custody to Scientific Analytical Institute, Inc. (SAI), for independent analysis of RCRA metals according to NIOSH method 7300. SAI is accredited by the American Industrial Hygiene Association (AIHA) utilizing the Industrial Hygiene Proficiency Analytical Testing (IHPAT) program. SAI's AIHA IHPAT Laboratory identification number is 173190.

Results of the air sampling are summarized in the table below by identifying the range of results for Building 103E for each of the seven (7) metals that were sampled. Samples with a "<" sign indicate that the results were below the laboratory's method reporting limit.

Analysis	Lowest	Highest
	Concentration	Concentration
	$(\mu g/m^3)$	$(\mu g/m^3)$
Silver Ag	< 5.6	< 5.6
Arsenic As	< 0.77	< 0.77
Barium Ba	< 0.56	< 0.56
Cadmium Cd	< 0.077	< 0.077
Total Chromium Cr	< 5.6	<5.6
Lead Pb	< 0.40	< 0.40
Selenium Se	< 0.77	< 0.77

Results indicate that **all** of the eight (8) air samples collected contained concentrations of RCRA metals below the laboratory method limit of detection or the OSHA Permissible Exposure Limit (PEL). Sample locations and the corresponding result are summarized in the enclosed in the laboratory analytical results are included in the attached tables. The air sampling professional's Missouri Lead license is in included in Appendix B.

It should be noted that this air sampling investigation was only a screening of airborne RCRA metals and should not be interpreted or used to determine compliance or non-compliance with OSHA personnel monitoring regulations.

OCCU-TEC appreciates the opportunity to work with GSA on this project. If you have any questions concerning this report, or if we may be of any additional service, please feel free to contact us.

Sincerely. (b) (6)

Justin Arnold Environmental Scientist (b) (6)

Kevin Heriford Project Manager (QA/QC)

Appendices:

A: Laboratory Analytical Results and Chain of Custody Documentation

B: Qualifications and Licenses

Appendix A

Laboratory Analytical Report and Chain of Custody Documentation





Project:

Airborne Metals Concentration by Inductively-Coupled Plasma Analysis (ICP)



NIOSH Method 7300

Attn:

Client: Occu-Tec, Inc.

918004.002

In

Justin Arnold

Lab Order ID:

Page:

11809540 04/17/2018

100 NW Business Park Ln. Riverside, MO 64150 Date Received: Date Reported: Date Amended:

04/27/2018 05/02/2018

1 of 3

Sample ID	Description	Volume (L)		Reporting Limit (µg)	Concentration (µg)	Concentration (µg/m³)
Lab Sample ID	Lab Notes					
	1 st Floor	323.2	Ag	1.8	<1.8	<5.6
			As	0.25	< 0.25	< 0.77
103E-MetA18-			Ba	0.18	<0.18	< 0.56
01	column P20		Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	< 5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_1			Se	0.25	< 0.25	< 0.77
		323.2	Ag	1.8	<1.8	<5.6
	2 nd Floor column P20		As	0.25	< 0.25	< 0.77
103E-MetA18-			Ba	0.18	<0.18	< 0.56
02			Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	< 5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_2			Se	0.25	< 0.25	<0.77
	1 st Floor column L28 1/2	column L28	Ag	1.8	<1.8	<5.6
			As	0.25	< 0.25	< 0.77
103E-MetA18-			Ba	0.18	<0.18	<0.56
03			Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	< 5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_3			Se	0.25	< 0.25	<0.77

Melissa Ferrell/Daniel Olson

(b) (6)

Analyst

Lab Director

This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by AIHA or any other agency of the U.S. government. Scientific Analytical Institute participates in the AIHA IHPAT program. IHPAT Laboratory ID: 173190. Unless otherwise noted blank sample correction was not performed on analytical results. MDLs are available upon request. Reporting limits stated above.



Airborne Metals Concentration by Inductively-Coupled Plasma Analysis (ICP)



NIOSH Method 7300

Attn:

Client: Occu-Tec, Inc.

.

Justin Arnold

Lab Order ID:

11809540 04/17/2018

100 NW Business Park Ln. Riverside, MO 64150 Date Received: Date Reported: Date Amended:

04/27/2018 05/02/2018

Project: 918004.002

Page: 2 of 3

Sample ID	Description	Volume (L)		Reporting Limit (µg)	Concentration (µg)	Concentration (µg/m³)
Lab Sample ID	Lab Notes					
			Ag	1.8	<1.8	< 5.6
	1 st Floor	323.2	As	0.25	< 0.25	< 0.77
103E-MetA18-			Ba	0.18	<0.18	< 0.56
04	column N27		Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	< 5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_4			Se	0.25	< 0.25	< 0.77
			Ag	1.8	<1.8	< 5.6
			As	0.25	< 0.25	<0.77
103E-MetA18-	2 nd Floor	323.2	Ba	0.18	< 0.18	< 0.56
05	column N28		Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	<5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_5			Se	0.25	< 0.25	< 0.77
		2 nd Floor column P27 323.2	Ag	1.8	<1.8	<5.6
			As	0.25	< 0.25	< 0.77
103E-MetA18-	2 nd Floor		Ba	0.18	<0.18	<0.56
06	column P27		Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	< 5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_6			Se	0.25	<0.25	<0.77

Melissa Ferrell/Daniel Olson

(b) (6)

Analyst

Lab Director

This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by AIHA or any other agency of the U.S. government. Scientific Analytical Institute participates in the AIHA IHPAT program. IHPAT Laboratory ID: 173190. Unless otherwise noted blank sample correction was not performed on analytical results. MDLs are available upon request. Reporting limits stated above.



Project:

Airborne Metals Concentration by Inductively-Coupled Plasma Analysis (ICP)



NIOSH Method 7300

Occu-Tec, Inc. **Client:**

100 NW Business Park Ln.

Riverside, MO 64150

918004.002

Attn: **Justin Arnold**

Lab Order ID: **Date Received:** 11809540

Date Reported: Date Amended:

04/17/2018 04/27/2018

Page:

05/02/2018

3 of 3

	Description	Volume (L)	Element	Reporting Limit (µg)	Concentration (µg)	Concentration (µg/m³)
	Lab Notes					
103E-MetA18- 07	Exterior Roof	323.2	Ag	1.8	<1.8	< 5.6
			As	0.25	< 0.25	< 0.77
			Ba	0.18	<0.18	< 0.56
			Cd	0.025	< 0.025	< 0.077
			Cr	1.8	<1.8	< 5.6
			Pb	0.13	<0.13	< 0.40
11809540IPA_7			Se	0.25	<0.25	< 0.77
103E-MetA18- 08	Blank	-	Ag	1.8	<1.8	-
			As	0.25	< 0.25	-
			Ba	0.18	<0.18	-
			Cd	0.025	< 0.025	-
			Cr	1.8	<1.8	-
			Pb	0.13	<0.13	-
11809540IPA_8			Se	0.25	< 0.25	-

Melissa Ferrell/Daniel Olson

Analyst

(b) (6)

Lab Director

This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by AIHA or any other agency of the U.S. government. Scientific Analytical Institute participates in the AIHA IHPAT program. IHPAT Laboratory ID: 173190. Unless otherwise noted blank sample correction was not performed on analytical results. MDLs are available upon request. Reporting limits stated above.

Appendix B Qualifications and Licenses





Missouri Department of Health and Senior Services

P.O. Box 570, Jefferson City, MO 65102-0570 Phone: 573-751-6400 FAX: 573-751-6010 RELAY MISSOURI for Hearing and Speech Impaired 1-800-735-2966 VOICE 1-800-735-2466



Jeremiah W. (Jay) Nixon Governor

Peter Lyskowski Acting Director

May 27, 2016

Justin Arnold Occu-Tec, Inc. 100 NW Business Park Lane Riverside, MO 64150

Dear Licensee:

After review of your renewal application for a license with the Missouri Department of Health and Senior Services' Lead Licensing Program, your application for a Lead Risk Assessor license has been approved.

Enclosed is your Lead Risk Assessor license certificate and photo identification badge. Please have your identification badge with you at all times while conducting lead abatement activities.

Note the date your Lead Risk Assessor license expires. A renewal application and information will be mailed to you approximately three months before your license expiration date and will need to be completed and submitted 60 days prior to the expiration date.

A requirement of renewing your application will be attending a Lead Risk Assessor refresher class. A list of Missouri accredited lead abatement training providers will be included in your renewal packet. Additional information on training and lead abatement in general can be found at http://health.mo.gov/safety/leadlicensing/index.php.

Please contact the Lead Licensing Program at (573) 526-5873 or (888) 837-0927 if you have any questions concerning this letter or on lead abatement regulations in general.

Sincerely,

(b) (6)

Angie DeBroeck Lead Licensing Program

AKD:ss

Enclosures

Missouri Department of Health and Senior Services

Lead Occupation License - ID Badge License Number: 120611-300003622

Lead Risk Assessor

JUSTIN ARNOLD

Expiration Date: 06/11/2018

www.health.mo.gov

Healthy Missourians for The Missouri Department of Health and Senior Services will be the leader

