

January 11, 2022

Diane Czarnecki Industrial Hygienist Facilities Management Division GSA Public Buildings Service – Heartland Region 2300 Main Street Kansas City, MO 64108

Re: Goodfellow Federal Center – Bldg. 102E Air Sampling Project No. 121244

Dear Ms. Czarnecki:

Thank you for the opportunity to provide the General Services Administration (GSA) with the Resource Conservation and Recovery Act (RCRA) metals air sampling investigation of the above referenced building located at the Goodfellow Federal Complex, in St. Louis, Missouri. Burns & McDonnell understands that the purpose of the investigation was to provide sampling data regarding existing conditions to supplement previous investigation reports prepared for the facility. The following report summarizes air-sample collection activities and the laboratory analytical results of the samples submitted.

METHODOLOGY

On November 29, 2021, Ashley Anstaett and Emily Pulcher of Burns & McDonnell conducted area air-sampling for the presence of seven (7) of the RCRA metals including arsenic, barium, cadmium, chromium, lead, selenium, and silver. Sampling was conducted in various locations throughout Building 102E.

The sampling plan, number of samples, sample distribution, and general methodology was developed based on previous investigation methodology and in coordination with the GSA. Sample locations and samples collected from discretionary locations were determined by sampling personnel while on-site.

Air samples for RCRA metals were collected on 37-millimeter (mm) cassettes with 0.8 micrometer (µm) mixed cellulose ester (MCE) filters, using powered air sampling pumps, in accordance with the National Institute for Occupational Safety and Health (NIOSH) Method 7300. The sampling strategy included collecting a minimum sample volume of 500 liters based on the calibrated pump flow rate and sample duration. Air samples were submitted under chain-of-custody to Environmental Hazards Services, LLC (EHS) in Richmond, Virginia for independent analysis of 7 RCRA metals according to NIOSH method 7300. EHS is accredited under the American Industrial Hygiene Association (AIHA) Industrial Hygiene Laboratory Accreditation Program (IHLAP) program, identification number LAP-100420.



Diane Czarnecki Facilities Management Division January 11, 2022 Page 2

RESULTS AND DISCUSSION

Results of the air sampling are summarized in the table below by identifying the range of results for Building 102E for each of the seven (7) metals that were sampled. Results indicate that all 9 air samples collected from Building 102E and analyzed for RCRA metals were below their respective OSHA Permissible Exposure Limit (PEL), as based on a time-weighted-average.

Table 1. Summary of Air Sampling Results

Analyte	Lowest Concentration ^(a) (μg/m ³) ^(b)	Highest Concentration ^(a) (μg/m ³) ^(b)	Permissible Exposure Limit (PEL) (μg/m³) ^(b)				
Arsenic	<0.26	< 0.30	10				
Barium	< 0.26	< 0.30	500				
Cadmium	< 0.052	< 0.059	5				
Chromium (Total)	<1.3	<1.5	500				
Lead	< 0.26	< 0.30	50				
Selenium	<1.3	<1.5	200				
Silver	< 0.26	< 0.30	10				

Notes:

- (a) Samples with a "<" sign indicate that the results were below the laboratory's reporting limit, which varies based on sample air volume.
- (b) $\mu g/m^3 = \text{micrograms per cubic meter of air.}$

GSA may choose to compare results with guidance limits from additional organizations for risk evaluation, including but not limited to the American Conference of Governmental Industrial Hygienists (ACGIH) and/or the World Health Organization (WHO).

A summary table of all sampling results by location is included in Appendix A. The complete laboratory report for the air sampling from EHS is attached in Appendix B.

LIMITATIONS

The scope of this assessment was limited as follows. Burns & McDonnell collected samples from a select number of locations in an effort to minimize cost while providing a general overview of the air quality at the site. Sample locations do not encompass every indoor space at the site. Additionally, based on previous sampling history, samples were only analyzed for a select number of potential contaminants likely to affect the air quality at the site. Burns &



Diane Czarnecki Facilities Management Division January 11, 2022 Page 3

McDonnell is not responsible for potential contaminants not identified in this report. This report was prepared for the sole use of GSA.

Burns & McDonnell appreciates the opportunity to work with the General Services Administration on this project. Please contact us if you have any questions regarding this report or if we may be of any additional service.

Sincerely,



Matt Shanahan, CHMM Project Manager

Attachments:

Appendix A – Results Summary by Location Appendix B – Air Sample Laboratory Report

Information in Appendices A and B is not accessible for people using screen reader technology. If this information is required, it can be furnished upon request by contacting 816-223-6198 or red-en-vironmental@gsa.gov.



Appendix A Results Summary by Location

Sample Number	Location	Analyte	Result	Units	Recommended Limits ¹
102E-A-01	1st floor, N lobby, windowsill outside office entrance	Arsenic	< 0.27	μg/m³	10
		Barium	< 0.27	μg/m³	500
		Cadmium	< 0.053	μg/m³	5
		Chromium	< 1.4	μg/m³	500
		Lead	< 0.27	μg/m³	50
		Selenium	< 1.4	μg/m³	200
		Silver	< 0.27	μg/m³	10
102E-A-02	1st floor, storage room, shelf on N wall	Arsenic	< 0.27	μg/m³	10
		Barium	< 0.27	μg/m³	500
		Cadmium	< 0.053	μg/m³	5
		Chromium	< 1.4	μg/m³	500
		Lead	< 0.27	μg/m³	50
		Selenium	< 1.4	μg/m³	200
		Silver	< 0.27	μg/m³	10
102E-A-03	1st floor, break room, table	Arsenic	< 0.26	μg/m³	10
		Barium	< 0.26	μg/m³	500
		Cadmium	< 0.052	μg/m³	5
		Chromium	< 1.3	μg/m³	500
		Lead	< 0.26	μg/m³	50
		Selenium	< 1.3	μg/m³	200
		Silver	< 0.26	μg/m³	10
102E-A-04	1st floor, printer area, top of cabinet on E wall	Arsenic	< 0.27	μg/m³	10
		Barium	< 0.27	μg/m³	500
		Cadmium	< 0.053	μg/m³	5
		Chromium	< 1.4	μg/m³	500
		Lead	< 0.27	μg/m³	50
		Selenium	< 1.4	μg/m³	200
		Silver	< 0.27	μg/m³	10
102E-A-05	1st floor, conference room table	Arsenic	< 0.27	μg/m³	10
		Barium	< 0.27	μg/m³	500
		Cadmium	< 0.053	μg/m³	5
		Chromium	< 1.4	μg/m³	500
		Lead	< 0.27	μg/m³	50
		Selenium	< 1.4	μg/m³	200
		Silver	< 0.27	μg/m³	10

Appendix A Results Summary by Location

Sample Number	Location	Analyte	Result	Units	Recommended Limits ¹
102E-A-06	1st floor, lab room, top of desk on S wall	Arsenic	< 0.28	μg/m³	10
		Barium	< 0.28	μg/m³	500
		Cadmium	< 0.055	μg/m³	5
		Chromium	< 1.4	μg/m³	500
		Lead	< 0.28	μg/m³	50
		Selenium	< 1.4	μg/m³	200
		Silver	< 0.28	μg/m³	10
102E-A-07	1st floor, S lobby, top of wood door sill	Arsenic	< 0.30	μg/m³	10
		Barium	< 0.30	μg/m³	500
		Cadmium	< 0.059	μg/m³	5
		Chromium	< 1.5	μg/m³	500
		Lead	< 0.30	μg/m³	50
		Selenium	< 1.5	μg/m³	200
		Silver	< 0.30	μg/m³	10
102E-A-08	2nd floor, top of orange wall in S office area	Arsenic	< 0.26	μg/m³	10
		Barium	< 0.26	μg/m³	500
		Cadmium	< 0.052	μg/m³	5
		Chromium	< 1.3	μg/m³	500
		Lead	< 0.26	μg/m³	50
		Selenium	< 1.3	μg/m³	200
		Silver	< 0.26	μg/m³	10
102E-A-09	Field blank	Arsenic	< 0.15	μg	
		Barium	< 0.15	μg	
		Cadmium	< 0.030	μg	
		Chromium	< 0.75	μg	
		Lead	< 0.15	μg	
		Selenium	< 0.75	μg	
		Silver	< 0.15	μg	

Notes:

¹Limits equal to the Occupational Safety and Health Administration (OSHA) Permissible Exposure Limits (PELs)





Environmental Hazards Services, L.L.C. 7469 Whitepine Rd Richmond, VA 23237

Telephone: 800.347.4010

Air Metals Analysis Report

Client: Burns & McDonnell Engineering

9400 Ward Pkwy.

Kansas City, MO 64114

Report Number: 21-12-00470

Received Date: 12/03/2021 Reported Date: 12/09/2021

Project/Test Address: 168765; GFC; 4300 Goodfellow Blvd

Client Number: 26-3514 Laboratory Results

Fax Number: 816-822-3494

Lab Sample Number	Client Sample Number	Analyzed Date	Analyte	Air Volume (L)	Total Metal (ug)	Concentration (ug/m³)	Narrative ID
21-12-00470-001	102E-A-01	12/08/2021	Arsenic (As)	568	<0.15	<0.27	
			Barium (Ba)		<0.15	<0.27	
			Cadmium (Cd)		<0.030	<0.053	
			Chromium (Cr)		<0.75	<1.4	
			Lead (Pb)		<0.15	<0.27	
			Selenium (Se)		<0.75	<1.4	
			Silver (Ag)		<0.15	<0.27	
21-12-00470-002	102E-A-02	12/08/2021	Arsenic (As)	576	<0.15	<0.27	
			Barium (Ba)		<0.15	<0.27	
			Cadmium (Cd)		<0.030	<0.053	
			Chromium (Cr)		<0.75	<1.4	
			Lead (Pb)		<0.15	<0.27	
			Selenium (Se)		<0.75	<1.4	
			Silver (Ag)		<0.15	<0.27	
21-12-00470-003	102E-A-03	12/08/2021	Arsenic (As)	585	<0.15	<0.26	
			Barium (Ba)		<0.15	<0.26	
			Cadmium (Cd)		<0.030	<0.052	

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 21-12-00470

Project/Test Address: 168765; GFC; 4300 Goodfellow Blvd

Lab Sample Number	Client Sample Number	Analyzed Date	Analyte	Air Volume (L)	Total Metal (ug)	Concentration (ug/m³)	Narrative ID
			Chromium (Cr)		<0.75	<1.3	
			Lead (Pb)		<0.15	<0.26	
			Selenium (Se)		<0.75	<1.3	
			Silver (Ag)		<0.15	<0.26	
21-12-00470-004	102E-A-04	12/08/2021	Arsenic (As)	576	<0.15	<0.27	
			Barium (Ba)		<0.15	<0.27	
			Cadmium (Cd)		<0.030	<0.053	
			Chromium (Cr)		<0.75	<1.4	
			Lead (Pb)		<0.15	<0.27	
			Selenium (Se)		<0.75	<1.4	
			Silver (Ag)		<0.15	<0.27	
21-12-00470-005	102E-A-05	12/08/2021	Arsenic (As)	574	<0.15	<0.27	
			Barium (Ba)		<0.15	<0.27	
			Cadmium (Cd)		<0.030	<0.053	
			Chromium (Cr)		<0.75	<1.4	
			Lead (Pb)		<0.15	<0.27	
			Selenium (Se)		<0.75	<1.4	
			Silver (Ag)		<0.15	<0.27	
21-12-00470-006	102E-A-06	12/08/2021	Arsenic (As)	550	<0.15	<0.28	
			Barium (Ba)		<0.15	<0.28	
			Cadmium (Cd)		<0.030	<0.055	
			Chromium (Cr)		<0.75	<1.4	
			Lead (Pb)		<0.15	<0.28	
			Selenium (Se)		<0.75	<1.4	
			Silver (Ag)		<0.15	<0.28	

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 21-12-00470

Project/Test Address: 168765; GFC; 4300 Goodfellow Blvd

Lab Sample Number	Client Sample Number	Analyzed Date	Analyte	Air Volume (L)	Total Metal (ug)	Concentration (ug/m³)	Narrative ID
21-12-00470-007	102E-A-07	12/08/2021	Arsenic (As)	512	<0.15	<0.30	
			Barium (Ba)		<0.15	<0.30	
			Cadmium (Cd)		<0.030	<0.059	
			Chromium (Cr)		<0.75	<1.5	
			Lead (Pb)		<0.15	<0.30	
			Selenium (Se)		<0.75	<1.5	
			Silver (Ag)		<0.15	<0.30	
21-12-00470-008	102E-A-08	12/08/2021	Arsenic (As)	585	<0.15	<0.26	
			Barium (Ba)		<0.15	<0.26	
			Cadmium (Cd)		<0.030	<0.052	
			Chromium (Cr)		<0.75	<1.3	
			Lead (Pb)		<0.15	<0.26	
			Selenium (Se)		<0.75	<1.3	
			Silver (Ag)		<0.15	<0.26	
21-12-00470-009[102E-A-09	12/08/2021	Arsenic (As)		<0.15		
			Barium (Ba)		<0.15		
			Cadmium (Cd)		<0.030		
			Chromium (Cr)		<0.75		
			Lead (Pb)		<0.15		
			Selenium (Se)		<0.75		
			Silver (Ag)		<0.15		

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 21-12-00470

Project/Test Address: 168765; GFC; 4300 Goodfellow Blvd

Lab Sample Client Sample Analyzed Analyte Air Total Metal Concentration Narrative Number Date Volume (L) (ug) (ug/m³) ID

Sample Narratives:

Method: NIOSH 7300M Analyst: Kailee Guthrie

(b) (6)

Reviewed By Authorized Signatory:

Melissa Kanode QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contains less than the reporting limit for each particular metal, based on a 15mL volume. The reporting limit is 0.03ug for Cadmium, 0.15ug for Arsenic, Barium, Lead and Silver, and 0.75ug for Chromium and Selenium.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Unless otherwise noted, samples are reported without a dry weight correction. Sample location, description, area, volume, etc., was provided by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. NY ELAP #11714.

LEGEND ug = microgram ug/m³ = micrograms per cubic meter
mL = milliliter L= Liters

ENVIRONMENTAL HAZARDS SERVICES, LLC

			Μe	<u>:ta</u>	ls	Ch	ai	n (of	Custody F	orr	n					Pg	(of
	Company Name	Burns & McD	onr	ıell		***************************************					Acc	oun							
Co	ompany Address	9400 Ward P		wa	У					Ci	ity/Sta	ate/							
	Phone	314-302-466										Em	Email eapulcher@burnsmcd.com						
Р	roject Name / Te	1	FC /	/ 43	00	God	odfe	ello\	Total Carlo		#*************************************								
	PO Number	168765			1,5 - 1,5 - 1				C	ollected By As	hlei	41	Ans	ta	et	t BEI	mily	Pul	lcher
Tui	rn-Around Time		1	ि 3	DAY	, j	(2 D	ΑΥ	ℂ 1 DAY		ि	MAG	E DA	ιY O	R WEEK	KEND -	Must C	all Ahead
	Т		7133333						- Salestia		-13388			****		I .			1
					Μ	ETA	LS				P	PART	ICUL	_ATES	S		AIR		WIPES
AB NUMBER	Client	Collection		A 8	otal	Profile	e Profile		Total		ce Dust	Dust	netric		-	Total Time	Flow Rate	Vol.	AREA
LAB1	Sample ID	Date & Time	Pb TCLP	TCLP RCRA 8	RCRA 8 Total	Toxic Metal Profile	Welding Fume Profile	TX 11 TCLP	CA 17 To	Other Metals	Total Nuisance Dust	Respirable Dust	TSP Gravimetric	TSP Pb	PM-10	Mins.	L/min.	Total Liters	Circle The Unit of Measurement Used cm or in
						ř	Š			Ag, As, Ba, Cd, Cr,									
1	102E-A-01		$\perp \perp$						<u> </u>	Ag, As, Ba, Cd, Cr, Pb, Se						227	2.5	 	X
2	102E-A-02	1048	$\perp \perp$						<u> </u>							226	T	576	Х
3	102E-A-03	1049							<u> </u>							225	T		X
4	102E-A-04	1049							ļ							226	1	576	х
5	102E-A-05	1050	igsqcup						<u></u>							225		574	X
6	102E-A-06	105%							<u> </u>							220	2.5	550	х
7	102E - A - 07	1054							<u></u>							197	2.6	512	x
8	102E-A-08	1056					ļ									225	2.0	585	x
9	102E-A-09	1 1036							<u></u>	1						NA	NA	NA	х
10																			x
11																			×
12																			x
13																			х
14																			x
15																			x
	Released By:	Emily Pula	<u> </u>	er						Date: 12	121	2	1			Time:	: 160	<u> </u>	
		(b) (6)													***************************************				
						L	AB U	SE O	NLY -	- BELOW THIS LINE					-				
Rece	Received By:																		
Signa	ature:	(b) (6)					4								1 14 f	21-12	2-004	70	
Date	: 12,3	/			<u>:</u>				С	AM DYPM				MATERIAL PROPERTY OF THE PROPE					
	Portal Contact A	Added														Due 1		ia	
8	7469 WHITEPIN	NE RD, RICHMOND,	, VA	232	37	(80	0)-3	47-4	4010								iday)	, •	

MM-L

EL

RESULTS VIA CLIENT PORTAL AVAILABLE @ www.leadlab.com