




U.S. General Services Administration

# Calexico West LPOE

Community Representatives Committee Meeting

GSA Public Buildings Service



# Phase 2A

UNITED STATES COURTHOUSE

# Calexico West LPOE Phase 2A Update

- Construction completed February 29, 2024
  - 16 primary inspection lanes
  - Pre-primary inspection canopy
  - Administrative building
  - 5 Southbound vehicle inspection booths
- Art Work to be installed by end of 2024



# Northbound Vehicle Inspection Booths



# Northbound Pre-Primary Vehicle Inspection Canopy



# Southbound Vehicle Inspection Booths



# Art in Architecture Commission

- Rendering of art work to be installed.
- Location - East corner as you exit the port - 2nd St and Cesar Chavez Blvd.
- Estimate of installation of art work is end of 2024.





# Phase 2B

UNITED STATES COURTHOUSE

# Calexico West LPOE Phase 2B Update

- Construct temporary pedestrian processing facility and pathway to current border crossing
- Demolish existing pedestrian processing and northbound vehicle inspection building.
- Construct new pedestrian processing facility, with up to 12 inspection lanes.



# Temporary Pedestrian Processing Configuration

